

PRODUCT INFORMATION

Style: Handguard II

Sizing:	Size	Part #	Overedge
			<u>White</u>
	XXSmall	134147	134851
	XSmall	333019	134852
	Small	333021	134853
	Medium	333023	134854
	Large	333025	134855
	XLarge	333027	134856



Registered Brand Name: Whizard®
Classification: Cut Resistant

PRODUCT DESCRIPTION

Description: Heavy Duty Cut Glove
Color: Available In White and Gray
Material: Ultra High Strength Fibers and Stainless Steel
CFR21 - Approved for Food Contact

Sold by: Piece
Packaging (Inner Pack): 6 Pieces
Packaging (Case Pack): 72 Pieces

CUT PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM F1790-97
Test Results: 10.17 lbs. / 4613 grams
ANSI Level 5

ABRASION PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM D3884-05
Test Results: 3950 revs (cycles)

WASHING INSTRUCTIONS

Always wash similar products of the same materials together. This will eliminate different material types from being effected by non-recommended chemicals. Rinse all gloves thoroughly in cold water to ensure the release of particles in the products. If pre-soaking use luke warm water to ensure good particle softening. Mild detergents or chemicals should be used to enhance the laundering process. All products should be laundered using a mild soap and detergent. Use a warm water wash with a temperature not to exceed 160°F (71°C). Wash time should not be longer than 15 to 20 minutes. Use a rinse cycle for the product in cold water. Repeat above as often as needed to ensure a thoroughly clean product. It is important to use a high extraction speed to thoroughly remove all excess moisture. Tumble dry glove in a temperature not higher than 150°F (67°C) for a time of 15 to 20 minutes; adjustments in dry time may increase depending on quantity and weight of the products. Temperatures should not exceed 150°F (67°C).

CAUTION

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.